

செயற்கமி
எண் 2776
ததி 12.08.14
கொடிகலன் பராமரிப்பு / துறையுறை

OFFICE OF THE ASST. ENGINEER
C.R.No. 597
10 AUG 2014
TTPS
BOILER MAINTENANCE SUB DIV IV

TANGEDCO

OFFICE OF THE ASST. EXECUTIVE ENGINEER
C.R.No.
10 AUG 2014
TTPS
BOILER MAINTENANCE SUB DIV IV

From
Er. S. Aribu Sulthan, B.E., M.B.A.,
Superintending Engineer,
Mechanical-II,
TTPS,
Tuticorin - 04.

To
The Superintending Engineer,
Purchase and Administration,
TTPS,
Tuticorin-04.

AEE-4
12/08/14
EE | BM

Lr. No. SE / M-II / TTPS / F. / D.3 / 2014, dt. 8 .08.2014.

Sir,

Sub : TTPS - BM -Supply of spares for Air Pre heater support bearing of Unit IV- Performance report furnished- Reg.

Ref : 1.Lr.No.SE/P&A /EE/MM/TTPS /AEE5/F.Enq.2124-M/D.3435/14
dt.23.07.14.
2.P.O.No.4944-M:CE/TTPS/SE/P&A/EE/MM/AEE5/D.2643/09
Dt.04.07.2009

Vide reference 2nd cited above, one set support bearing housing assembly with bearing 294/500 and 1 no. cold end stationery spool assembly were supplied by M/s Geeco Enercon Pvt. Limited, Trichy, on 11.02.2010. This support bearing housing assembly with bearing 294/500 was erected in Air Pre Heater B of unit V during May .2010 and the performance is found to be satisfactory till date.

This is for favour of further action please.

AS/SE
23/8/14

[Signature]
080814
Superintending Engineer,
Mechanical-II/TTPS.

Copy to EE/BM/TTPS.(2 Copies)

[Signature]